

15 October 1997
C1-Q6C-SL-97-344

California Regional Water Quality Control Board
Los Angeles Region
101 Centre Plaza Drive
Monterey Park, CA 91754



Attention: Technical Support Unit

Subject: **TECHNICAL MONITORING REPORT: NPDES PERMIT NO.
CA0001414 COMPLIANCE FILE NO. 5999 - 3RD QUARTER 1997**

Gentlemen:

Douglas Aircraft Company herewith submits the technical report on self monitoring work performed in accordance with the specifications contained in Monitoring and Reporting Number 5999. The enclosures summarize the third quarter 1997 reporting period for the Torrance, California facility.

All analyses were conducted by Truesdail Laboratories, Inc. of Tustin, California, in accordance with the current EPA guideline procedures as specified in the Monitoring Program.

No samples were collected this quarter because of no flow conditions.

Please contact the undersigned at (562) 593-3902 if you have any questions regarding this submittal.

"I declare under penalty of perjury that the foregoing is true and correct", executed on the 15th of October, 1997.

Sincerely,

A handwritten signature in cursive script, appearing to read 'Scott Lattimore'.


Scott Lattimore
Environmental Engineer
Safety, Health, and Environmental Affairs

DOUGLAS AIRCRAFT COMPANY
19503 S. NORMANDIE AVE.
TORRANCE, CA. 90502
COMPLIANCE FILE NO. 5999
NPDES PERMIT NO. CA0001414

THIRD QUARTER 1997

COMPLIANCE WITH STORM DRAIN EFFLUENT LIMITS

PARAMETER	CONCENTRATION LIMITS		C6	C6	C6	DISCHARGE EXCEEDS LIMITS (Y/N)
	AVERAGE	MAXIMUM	7/3/97	8/14/97	9/5/97	
pH (pH units)	---	6.0 - 9.0	7.6	7.8	7.3	N
TEMPERATURE (F)	---	100	72	72	80	N
SUSPENDED SOLIDS (mg/l)	50	150				
SETTLEABLE SOLIDS (ml/l)	0.1	0.3				
BOD5 @ 20C (mg/l)	20	60				
OIL & GREASE (mg/l)	10	15				
CHROMIUM TOTAL (mg/l)		0.05				
TOTAL WASTE FLOW (gallons/day)			NO FLOW	NO FLOW	NO FLOW	



TRUESDAIL LABORATORIES, INC.
CHEMISTS - MICROBIOLOGISTS - ENGINEERS

14201 FRANKLIN AVENUE • TUSTIN, CALIFORNIA 92780
PHONE (714)730-6239 • FAX (714)730-6462

CLIENT: Douglas Corporation
3855 Lakewood Blvd.
Long Beach, CA 90846
ATTN: Scott Lattimore

REPORT

REPORT DATE: July 08, 1997

RECEIVED: July 03, 1997

LABORATORY NUMBER: 402857

SAMPLE DATE: 07/03/97
SAMPLE TIME: 08:45 AM
SAMPLE SITE: Torrance Stormdrain,
next to site #799
PERMIT NUMBER: NPDES #CA0001414

MONTHLY INDUSTRIAL WASTEWATER ANALYSIS, AS REQUESTED

RESULTS

Total Flow, GPD

No flow reported

Temperature, °F

72

Units (EPA 150.1)

7.6

Respectfully Submitted,
Truesdail Laboratories, Inc.

Julia Nayberg, Manager
Water and Waste Laboratory



This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these laboratories.



TRUESDAIL LABORATORIES, INC.
CHEMISTS - MICROBIOLOGISTS - ENGINEERS

14201 FRANKLIN AVENUE • TUSTIN, CALIFORNIA 92780
PHONE (714)730-6239 • FAX (714)730-6462

REPORT

CLIENT: Boeing
3855 Lakewood Blvd.
Long Beach, CA 90846
ATTN: Scott Lattimore

SAMPLE DATE: 08/14/97
SAMPLE TIME: 07:40 AM
SAMPLE SITE: Torrance Stormdrain,
next to site #799
PERMIT NUMBER: NPDES #CA0001414


REPORT DATE: August 27, 1997
RECEIVED: August 14, 1997
LABORATORY NUMBER: 403539


MONTHLY INDUSTRIAL WASTEWATER ANALYSIS, AS REQUESTED

RESULTS

Total Flow, GPD	No flow reported
Temperature, °F	72
pH, Units (EPA 150.1)	7.8

Respectfully Submitted,
Truesdail Laboratories, Inc.


Julia Nayberg, Manager
Water and Waste Laboratory



This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these laboratories.



TRUESDAIL LABORATORIES, INC.
CHEMISTS - MICROBIOLOGISTS - ENGINEERS

14201 FRANKLIN AVENUE • TUSTIN, CALIFORNIA 92780
PHONE (714)730-6239 • FAX (714)730-6462

REPORT

CLIENT: Boeing
3855 Lakewood Blvd.
Long Beach, CA 90846
ATTN: Scott Lattimore

REPORT DATE: September 10, 1997

RECEIVED: September 05, 1997

LABORATORY NUMBER: 403873


SAMPLE DATE: 09/05/97
SAMPLE TIME: 11:35 AM
SAMPLE SITE: Torrance Storm Drain,
next to site #799
PERMIT NUMBER: NPDES #CA0001414


MONTHLY INDUSTRIAL WASTEWATER ANALYSIS, AS REQUESTED

RESULTS

Total Flow, GPD	No flow reported
Temperature, °F	80
pH, Units (EPA 150.1)	7.3

Respectfully Submitted,
Truesdail Laboratories, Inc.


Julia Nayberg, Manager
Water and Waste Laboratory



This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public, and these laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these laboratories.